

## **Academy of Model Aeronautics**

5161 East Memorial Drive, Muncie, Indiana 47302 (765) 287-1256 – Voice • Competitions Fax (765) 286-3303 www.modelaircraft.org

EXHIBIT A RULI	ES CHANGE PROPOSAL FORM
PROPOSAL NO. (To be inserted by Headquarters)	RECEIVED DATE (To be inserted by Headquarters)
REVISE DATE	VERSION NUMBER
	HANGE PROPOSAL FORM  Wood of Street English (Chairman).  Chairman.
PROPOSAL TYPE (Check One): X Basic Cross Indi	icate Original Proposal Number
CL Racing CL Navy Carrier CL Aerob	door Free Flight
Brief summary of the proposed change.	
To add additional safety features to the aircraft in order competitors and crew. This proposal also falls in line w	to provide a safer environment to the pilot, spectators, fellow with the current FAI Sporting Code Sec. 5.1.11
Exact wording proposed for the rule book. (List par present rule book wording" to "exact wording requi	ragraph numbers where applicable. Example: Change "quote ired".

## ADD SECTION 6.9.1 TO THE SECTION 6 SAFETY REQUIREMENTS AS FOLLOWS:

6.9.1 – For electric powered models, the electric power circuit(s) must not be physically connected, before the starting time is begun and must be physically disconnected immediately after landing.

Logic behind proposed change, including alleged shortcomings of the present rules. State intent for future reference.

This change makes the flying field environment safer for contestants, judges, crew and certainly spectators during a contest. Revision 6.9.1 recognizes that for electric powered models, while throttle cut features can provide the function of a disarmed state, it is difficult for others to confirm that the transmitter is in the "throttle cut" position. Furthermore, inadvertent disabling of the throttle cut feature while the throttle stick is in any position other than the minimum position will result in potentially dangerous commanded power to the propeller. The model having a physical break in the connection between the batteries and the ESC/motor makes the disarmed state clear and insures that the motor cannot restart. According to the FAI policy, after landing, the batteries must immediately be physically disconnected prior to movement of the aircraft away from the runway.

New event test data/information (new events only), please provide what testing of this new event has taken place to include number of participants and number of contests.

<u>N/A</u>	
ect, if any, on current AMA records.	
<u>N/A</u>	
te: The Contest Board Chairman may, in coordination with mitting a proposal to the Contest Board for Final Vote, edit biguity provided the proposal intent is not changed.	
roposer <u>NSRCA sponsored proposal / Scott McHarg</u>	AMA #7511
treet Address 3819 Stony Creek Ln.	
treet Address <u>3819 Stony Creek Ln.</u> Sity_ <u>College Station</u>	
	State <u>TX</u> Zip <u>77845</u>